


# CROSS FEED DRUM CLEANERS



## Model year change 2016

The models up to serial number 126664 can be updated to the newer version. The scrapers avoid plugging at cross feed drums. Suggestion: modify the inner high feed drums.



### Installation time:

approx. 12 h



### Package contents:

- All necessary elements for the retrofit
- Installation instructions



For the correct usage please check the operating manual

Header type	Attachment number	Info
300plus series	LCA113701	LCA113702