

ROUND TUBE COB SAVERS

Model year change 2017

The models up to serial number 128911 can be updated to the newer version. Higher support (yellow arrow) enables better cob transportation.

Benefit:

- Reduces of the cob losses



Installation time:

from 3 to 6 h
(depending on type)



Package contents:

- All necessary elements for the retrofit
- Installation instructions



For the correct usage please check the operating manual

Header type	Position	Attachment number	Quantity of attachments	Info
345plus	inner drum	115181	1	LCA115183
360plus			2	
375plus			3	
390plus			4	
300plus series	outer drum	115182	1	LCA115182
475plus		115193	1	LCA115193